## W – MOTOR SERVICE, j.s.c.

## Airport Bubovice 267 18 post office KARLŠTEJN

## INFORMATION BULLTEIN

No. M4-III/36b M6-III/45b

**Relates to:** Possibilities of alternative using of the dynamo PALAX LUN 2111/600 V, 28 V / type 52 9082.11 with Voltage Regulator LUN 2141/600 V, 28 V / on the engines WALTER MINOR 4-III and WALTER MINOR 6-III during overhaul or as a substitute in the operation.

Reason:

- 1. Because the original dynamo SCINTILLA CTC 22A / 300 V. 28 V / with voltage regulator XNR 04 - YC2 are not available on the engines WALTER MINOR 4-III can be used dynamo PALAX LUN 2111/600 V, 28 V/ of Czech production together with Voltage Regulator LUN 2141
- 2. Driving of dynamo a full no. 0780652 / including the driving control box and all the parts, which belongs to this system / is the same for engines WALTER MINOR 6-III too, in which the dynamo PALAX LUN 2111 /600 V, 28 V/ is operated
- **Measures**: 1. Both attachment flanges on the drive box of the dynamo carefully check for cracks – visually by magnifier 6x magnifying. Increased attention dedicate the place around the hole for fixing the box on the engine and around the stud for attaching the dynamo on the box.
  - 2 Installation of dynamo on the engine has to be done according to "Instructions for installation dynamo PALAX LUN 2111 " see Annex

Costs:

paid by the user

Efficiency: the date of bulletin delivery

Josef Hrdlička v.r.	Ing. Karel Šíma v.r.
OTK	
W	MOTOR SERVICE
	M Vorášals zan

Bulletin started to be valid form day of acceptance Bubovice, 16.1.1995