

# W – MOTOR SERVICE , j.s.c.

Airport Bubovice  
267 18 post office KARLŠTEJN

INFORMATION BULLTEIN

No. M4-III/35/a  
M6-III/44/a

**Relates to:** Checking of Interior areas of engines to corrosion and update the operating period to overhaul and between the overhaul .

**Reason :** It was found that many Aircraft Operators during one year operate the minimum number of hours with insufficiently made preservation , which leads to considerable extending the operating time between overhaul , which lead to intensive creation of corrosion and a consequent reduction of an operating reliability of engines.

**Measures :** Engines, which will not operate destined operating time over 12 years must be sent to a Repair company WMS to transfer partial or complete Overhaul .

Partial repair will be transferred to the following conditions:

a / engines that operated during the period of 12 years from date of production, or after the transferring of overhaul less than 65% of operating time to overhaul

b / engine's status after the transferring of a control finding in a specialized company allows to convert partial repair in the specialised repair company approved by the CAA

c / if the condition of the engine do not permit a partial repair , an operator / owner / will be informed about this situation

Operator / owner / will decide and approve an execution of overhaul.

2 / Engine overhaul will be transferred , if an engine during 12 years period will operate 65 % or more from an approved overhaul period .

**Recommendation:** A control finding or a partial repair will be possible to perform :

a / by the technician of WMS upon the order

b / by a special company mandated by WMS and approved by the CAA

.....  
CAA

.....  
  
W – MOTOR SERVICE

**Efficiency:** the date of bulletin delivery  
Bubovice 1993