W-MOTOR SERVICE, s.r.o.

Bubovice airfield 267 18 Karlštejn

INFORMATION BULLETIN

No. M4/42b No. M6/51b

RELATES TO:

Cancellation of partial engine inspection at 50% TBO (300 or 400 hours as applicable) for M4-III and M6-III engines operated using Aeroshell W 100, Elf 100 AD or TOTAL AERO D 100 oil for the entire TBO interval.

REASONS: Based on the official inspections of engines after 500 hours SMOH and findings during overhauls of engines operated using the above oils.

MEASURES: No specific measures.

CARRIED OUT BY: Operator.

COSTS: None.

EFFECTIVE DATE: 01 September 2014.

Bubovice, 15 August 2014.

Copy for information to: Civil Aviation Authority

Ing. Karel Šíma

LOVALOTOR-SERVICE

S.T.O.

PART CZ.MF.0026

Letiště Bubovice 170
267 18 KARLŠTEJN